

Atornillador eléctrico 20ATORNI001MT SE 4000

No. Diagrama	Código	No. Referencia Metabo	Descripción
4	2000315013170	315013170	CARCASA ENGRANAJE
5	2000343391590	343391590	CASQUILLO DE COJINETE
8	2000141156280	141156280	ANILLO DE MUELLE
10	2000141163980	141163980	PASADOR CILÍNDRICO
11	2000141163990	141163990	PASADOR CILÍNDRICO
12	2000316041200	316041200	PORTA HERRAMIENTAS CPL.
18	2000320050470	320050470	SOPORTE BOLAS
24	2000310008940	310008940	INDUCIDO CPL. 120 V
27	2000341570060	341570060	TORN.ALOM.PARA CHAPA
28	2000343391660	343391660	CHAPA GUÍA AIRE
29	2000344496670	344496670	CORDÓN MANGUITO DE ASPIRACIÓN
30	2000344496680	344496680	CORDÓN MANGUITO DE ASPIRACIÓN
31	2000311010810	311010810	INDUCTOR C.BOBINA120V
32	2000344496660	344496660	CORDÓN MANGUITO DE ASPIRACIÓN
33	2000344496710	344496710	CORDÓN MANGUITO DE ASPIRACIÓN
36	2000316041830	316041830	KOHLE VOLLST. M. LAGERBUEGEL120V
37	2000317003420	317003420	MOTOR
40	2000343391570	343391570	CARCASA DE MOTOR
42	2000343391580	343391580	TAPA DE PUNO
43	2000343391670	343391670	GANCHO PARA ANDAMIOS
44	2000343391620	343391620	CORREDERA DE CONEX.

